

Universal Sample Cutter



Open the Lid of the cutting die and position your sample on the foam base.




Close the Lid and check the alignment of your sample.
Maximum sample width is the width of the cutting die.



Place the metal tray onto the bed of the universal cutter.



Place the cutting die on top of the metal tray with the open end of the die towards the roller. Push the cutting die into the rollers.



Once the cutting die has entered the rollers rotate the handle.



The cutting die will be pulled through the rollers.



Remove the waste material to leave the required samples.